

Volvo Car USA LLC
Technical Journal

Technical Journal Title SPA2 VCU Prior Approval		Ref. No. TJ 37401.1.1	
Issuer (Dept.) Technical Service		Issue Date 5/23/25	Status Date 5/27/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3681	
Function Description VCU1 Control unit		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

In response to TJ 37279 - VCU replacement, the VCU will now require Prior Approval before replacement.

Part Number: 36003871

If it is determined that the VCU needs to be replaced after all necessary fault-tracing has been completed, please follow the advice under "Service."

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed
71	Starting/Vehicle start-up is not possible
22	Diagnostic communication/Wired diagnostic connection to vehicle does not work
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-9999		-	0-0

SERVICE:

Please review TJ 37279 along with this TJ.

If you determine that a VCU replacement is necessary, please create a "Prior Approval" vehicle report with "VCU Prior Approval" in the title. Include a detailed description of the customer's concern and all of the fault-tracing steps that you have completed.

Retailer Technical Support will review the report and provide the approval if applicable.



Technical Journal 37401.1.1

Warranty claim info:

No warranty claim will be accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report to Retailer Technical Support to get technical prior approval for VCU replacement. Use the concern area "Vehicle Report" and the sub-concern area "Prior Approval", use function group 3681, and title the report "VCU Prior Approval".