

Technical Journal

TITLE:

DTC CEM B109A4A Incorrect BBS

REF NO: TJ 37416.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-06-23	STATUS DATE: 2025-06-23
FUNC GROUP: 3662	FUNC DESC: Burglar alarm equipment	Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If the DTC CEM-B109A4A is set without any other symptoms, follow advise under Service.

CEM - Central Electronic Module

BBS - Battery Backed-up Sounder

SW - Software

CSC Customer Symptom Codes

Code	Description
3P	Control system, ignition and fuel supply/Permanent DTC present/Emissions Test (Smog check)
XM	Alarm/Other alarm problems

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
CEM	B109A4A	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2025-9999		-	202349-999952

Technical Journal 37416.2.0

SERVICE:

Do not replace any parts, this is a SW issue.

This DTC is not valid, and it does not affect the function. Erase the DTC and release the vehicle back to the customer.

A SW solution is planned during 2025 quarter 4.

WARRANTY CLAIM INFO:

No warranty claim is accepted for this TJ.

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support needed Polestar", use function group 3662.