

Technical Service Bulletin (TSB)
R1L Radio Over The Air Update
From 62.00.23 To 62.00.29 Software Version

REFERENCE:	TSB: 08-208-25 GROUP: 08 - Electrical	Date:	July 3, 2025	REVISION:	-
VEHICLES AFFECTED:	2021 - 2025 (B1) Jeep Renegade This bulletin applies to vehicles built on or before February 03, 2025 (MDH 0203XX) equipped with a Global Telematics Box Module (Sales Code RDG) and Uconnect 5 NAV W 8.4" DISP (ROW-DAB) (Sales Code UPL).			MARKET APPLICABILITY: <input type="checkbox"/> NA <input type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to South America markets.	
CUSTOMER SYMPTOM:	Customers will not experience any symptoms. <ul style="list-style-type: none"> New software has been created to support a new radio model. 				
CAUSE:	Supplier change				

REPAIR SUMMARY:

This bulletin provides information regarding the latest FOTA update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software for will be updated from 62.00.23 to 62.00.29.

NOTE: The national launch for the FOTA is expected to begin June 03, 2025.

DISCUSSION:

Vehicles sold in South America can now receive software updates “over-the-air”. Updates to software will occur in a phased roll-out. The software is updated through a builtin cellular modem in the vehicle. Customers will see a notification on their radio screen when new software is available for their radio [Fig. 1](#). The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.

NOTE: This is an Information Only Technical Service Bulletin to inform the dealer how the FOTA update is performed. This document does not contain a LOP for reimbursement.

1. The vehicle needs to be in ‘park’ and the ignition in the off position.

2. If the customer selects “Update Now” they can shut off the vehicle and leave. The update will be completed automatically [Fig. 1](#).




Fig. 1
Software Update Screen

NOTE: This step may take several minutes to complete.

3. Upon completion of update, the radio will display a confirmation message [Fig. 2](#).




Fig. 2
Software Update Confirmation Screen

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.