

Document Title:	Repair of the Battery Fuse on ES12RK		
Document Type:	Technical Service Bulletin	Publication Date:	June 23, 2025
Document #:	25-02	Make and Model:	Ember E-Series Spark LE, 12RK
VINs Affected:	7RVTE1169SA003266 and 7RVTE1160SA003267, 7RVTE1163TA003409 to 7RVTE116XTA003438		
Flat Rate Code:	50000668	Model Year:	2025 and 2026
Pre-Auth Required:	No	Pictures Required:	Yes
Time Allowed:	Inspection: 0 hours Repair: 0.5 hours		

Material List			
Item Index	Ember Part Number	Description/Material Type	Quantity
1	35000155	FUSE 40 AMP ORANGE BLADE	1
2	N/A	NOTICE LABEL	1

I. Purpose

To provide instruction on replacing the battery fuse and applying a notice label to the power center, which is necessary for the proper operation of the system.

II. Responsibilities

Dealer Service Personnel:

Fully complete this procedure within the time allotted to include the verification of repair adequacy in accordance with the technical service bulletin requirements.


III. Process

Repair

1. Locate and remove the existing 20-amp battery fuse in Circuit #6 of the power center.
2. Install one (1) 40-amp fuse, Ember Item# 35000155, into Circuit #6 of the power center.



3. Apply the provided 'NOTICE' label to the outside of the power center.



Maintenance Recommendations/Other

Safety, education, and customer satisfaction are our primary concerns. Should you have any questions, please contact us at 844-732-4204 or by email at warranty@emberrv.com.