



SSM 54039 2025 Explorer - 2.3L EcoBoost - Turbocharger Oil Return Tube Removal Procedure Update

Some 2025 Explorer vehicles equipped with a 2.3L EcoBoost engine may require removal of the turbocharger oil return tube due to various concerns. Workshop Manual, Section 303-04 has been updated with improved turbocharger oil return tube removal and installation service procedure steps.