



STAR ONLINE PUBLICATION



Case Number: S2408000126 Rev. A

Release Date: July 2025

Symptom/Vehicle Issue: Diagnostic Trouble Code (DTC) B1A0A-00 Remote Keyless Entry (RKE) FOB 3 Performance

Technician Observation: Technician observed the Radio Frequency Hub (RFHUB) has set the above DTC as stored or active.

Discussion: Some vehicles may exhibit the above DTC that has set erroneously and with no associated owner complaints. It is **not** recommended to replace any parts for this concern, all service parts will perform the same. Engineering is aware of a software issue that may set this false DTC for FOB 3 Performance when there may not even be a FOB 3 programmed to the vehicle. A software update is expected to be released within the 3rd quarter of 2025 to correct this concern.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found