



Service Bulletin

Bulletin No.: PIT6274C

Date: July, 2025

PRELIMINARY INFORMATION

Subject: Interior Vision Camera System With DTC B1C48 B1C46 B020A

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2025 - 2026		All	All	All	All
Cadillac	LYRIQ	2025		All	All	All	All
Chevrolet	Blazer	2025 - 2026		All	All	All	All
Chevrolet	Blazer EV	2025 - 2026		All	All	All	All
Chevrolet	Equinox	2025 - 2026		All	All	All	All
Chevrolet	Equinox EV	2025 - 2026		All	All	All	All
Chevrolet	Silverado EV	2025 - 2026		All	All	All	All
Chevrolet	Suburban	2025		All	All	All	All
Chevrolet	Tahoe	2025		All	All	All	All
Chevrolet	Traverse	2025 - 2026		All	All	All	All
GMC	Acadia	2025 - 2026		All	All	All	All
GMC	Sierra EV	2025 - 2026		All	All	All	All
GMC	Terrain	2025 - 2026		All	All	All	All
GMC	Yukon	2025		All	All	All	All
GMC	Yukon XL	2025		All	All	All	All

Involved Region or Country	United States, Canada, Mexico and Europe
Additional Options (RPO)	UCV - Connected Cameras Non-Equipped
Condition	A customer may comment about a possible intermittent Service Camera System Message and upon diagnostics, any of the following DTCs may be set as current or history. B020A, B1C64 or B1C48
Cause	This is a false DTC and/or message due to a software anomaly.

Correction

Do not replace any parts at this time.

Engineering is aware of the concern.

The PI will be updated when a repair is available.

Until a fix is available, the concern cannot be corrected by clearing codes.

Version	4
Modified	11/04/2024 - Created on. 12/05/2024 - Updated Labor Operation. 01/08/2025 - Updated Models, Condition, RPO box, Labor and Cause. 07/16/2025 - Updated Model List.

