



# Service Bulletin

Bulletin No.: PIT6274C

Date: July, 2025

## PRELIMINARY INFORMATION

**Subject: Interior Vision Camera System With DTC B1C48 B1C46 B020A**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2025 - 2026		All	All	All	All
Cadillac	LYRIQ	2025		All	All	All	All
Chevrolet	Blazer	2025 - 2026		All	All	All	All
Chevrolet	Blazer EV	2025 - 2026		All	All	All	All
Chevrolet	Equinox	2025 - 2026		All	All	All	All
Chevrolet	Equinox EV	2025 - 2026		All	All	All	All
Chevrolet	Silverado EV	2025 - 2026		All	All	All	All
Chevrolet	Suburban	2025		All	All	All	All
Chevrolet	Tahoe	2025		All	All	All	All
Chevrolet	Traverse	2025 - 2026		All	All	All	All
GMC	Acadia	2025 - 2026		All	All	All	All
GMC	Sierra EV	2025 - 2026		All	All	All	All
GMC	Terrain	2025 - 2026		All	All	All	All
GMC	Yukon	2025		All	All	All	All
GMC	Yukon XL	2025		All	All	All	All

<b>Involved Region or Country</b>	United States, Canada, Mexico and Europe
<b>Additional Options (RPO)</b>	UCV - Connected Cameras Non-Equipped
<b>Condition</b>	A customer may comment about a possible intermittent Service Camera System Message and upon diagnostics, any of the following DTCs may be set as current or history. B020A, B1C64 or B1C48
<b>Cause</b>	This is a false DTC and/or message due to a software anomaly.

### Correction

Do not replace any parts at this time.

Engineering is aware of the concern.

The PI will be updated when a repair is available.

Until a fix is available, the concern cannot be corrected by clearing codes.

<b>Version</b>	4
<b>Modified</b>	11/04/2024 - Created on. 12/05/2024 - Updated Labor Operation. 01/08/2025 - Updated Models, Condition, RPO box, Labor and Cause. 07/16/2025 - Updated Model List.

