



Radio Over The Air Update from U39.13(C) to U39P.2 R1H
Software Version (FOTA)

7/21/2025

**VEHICLES
AFFECTED:**

2026 (DT) RAM 1500 Pickup

This bulletin applies to vehicles equipped with a Global Telematics Box Module (Sales Code RDG) and one of the following radios:

- Uconnect 5 Nav w 8.4" Display (USA) (Sales Codes UBL).
- Uconnect 5 Nav w 8.4" Display (CAN) (Sales Codes UEL).
- Uconnect 5 Nav w 12.0" Display (USA) (Sales Code UBQ)
- Uconnect 5 Nav W 12.0" Display (CAN) (Sales Code UEQ)
- Uconnect 5 NAV W 14.4" Display (USA) (Sales Code UBW)
- Uconnect 5 NAV W 14.4" Display (CAN) (Sales Code UEW)

MARKET APPLICABILITY:

- | | |
|--|------------------------------|
| <input checked="" type="checkbox"/> NA | <input type="checkbox"/> MEA |
| <input type="checkbox"/> SA | <input type="checkbox"/> IAP |
| <input type="checkbox"/> EE | <input type="checkbox"/> CH |

**CUSTOMER
SYMPTOM:**

Customers may experience one or more of the following:

- Navigation non-functional, not updating current position.
- Screen Off hard key inoperative, Soft key on radio screen still operational.