

|                            |   |
|----------------------------|---|
| <b>Field Action Number</b> | N25-250378 (652.80)   |
| <b>Release notes</b>       | <p>GM Update 652.80</p> <ul style="list-style-type: none"> <li>• Improvements to vehicle diagnostics.</li> <li>• Fixes to preserve battery life and improve charging.</li> <li>• Fixes to address issues with shifting.</li> <li>• Fixes for vehicle airflow in icy conditions.</li> <li>• Improvements to HVAC compressor performance.</li> </ul> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p> |
| <b>Model Year</b>          | 2024  |
| <b>Make</b>                | Cadillac  |
| <b>Model</b>               | Lyriq   |
| <b>Components</b>          | VICM (Vehicle Integration Control Module)   |