

Search Query - Fuel Filler Flap or Charge Socket Flap Sticks Or Cannot Be Opened

Topic number	LI88.60-P-079592
Version	1
Function group	88.60 - Exterior flaps
Date	7/30/25
Validity	Production date from 01.06.2024
Reason for change	

Complaint

Fuel filler flap/socket flap sticks, cannot be opened

Cause

Under analysis.

Remedy

Create TIPS case with fault description and videos of the flap sticking. Send the TIPS case to the Body/Chassis/Entertainment inbox.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms				
Body > Door/Flap > Fuel filler flap > Jammed				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
	Central locking motor, socket flap	H	8204W	

XENTRY Tips

	Central locking motor, socket flap, fender, rear	H	820HY	
	Central locking motor, fuel filler flap	H	82627	