

SS581715-TBB C2 Jouley Battery Replacement

Applicable Vehicles

FCCC/TBB EB2 School Bus Chassis

Symptoms

Alternative Part Retrofit.

Issue

Jouley buses built with A66-18872-000 Proterra HV battery include coolant plumbing and low voltage wiring that is incompatible with later model Proterra HV batteries. Performing this service solution will allow a suspected failed A66-18872-000 better to be replaced ball current HV battery components (may require additional updates). Replacement A66-24665-000 Proterra battery must be used and requires additional parts and re-routing of coolant plumbing as well as low voltage wiring updates.

Solution

See attachment for installation instructions for the re-routing of coolant plumbing and low voltage wiring updates to the Proterra 2170 cell high voltage battery.

Normal warranty applies using PFP# A66-18872-00 with SRT of 1.5hr labor.


Labels :

Busses

Add tags

Attachments



 0 Kudos

Comment