



**Thrive Roof Sealant Concern:**

Winnebago has come to the realization that some Thrive models may experience concerns with the Alpha Super Flex Seal.

<u>LABOR:</u>	<u>OPERATION CODE</u>	<u>LABOR ALLOWANCE</u>
Repair:	04058104	.5

Parts: Alpha Non-Sag Sealant 1010

Part number: 2007200101A

**Thrive Roof Sealant Inspection and Repair**

**Inspect all areas of the roof where sealant is present for potential defects.** Look for common issues such as bubbles, voids, sagging, cracks, or other irregularities in the sealant. Refer to the example images below for visual reference.

**Key areas to inspect include:**

- Roof vents
- Skylights
- Antennas
- Solar panels and solar wire passthroughs
- Plumbing vents
- TPO membrane seams

Carefully examine each of these areas to ensure the sealant is intact and free from damage or deterioration.

## Common Defects

### Voids:



### Cracking





Technical Service Bulletin # 2025-001

**Repair:**

1. Apply Alpha 1010 Non-Sag Sealant to all affected areas as noted in the inspection. Allow to dry and confirm application of the seal has corrected all defects.



**Corrected Repair Photos**

