

Campaign code:
L636-A.16.25

Campaign name:
Airbag ECU replacement

Model:
Urus SE and Urus Performante

Model Year:
2024, 2025

Markets:
Czech Republic, United States, United Kingdom, China, Italy, Germany, Switzerland.

VIN Involved:
ZPBEC3ZL5RLA37559, ZPBUD6ZL2SLA37468,
ZPBUD6ZL8SLA37491, ZPBED5ZLXSLA37507,
ZPBED5ZL2SLA37646, ZPBED5ZL8SLA38008,
ZPBED5ZL5SLA38855, ZPBED5ZL7SLA38873,
ZPBED5ZL0SLA38973, ZPBED5ZLXSLA38978.


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:
Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:
Following the continuous monitoring of the product, Automobili Lamborghini SpA noted that some vehicles may display the airbag warning light on the dashboard.

Solution for the field:
Replace the Control unit Airbag.

Spare Parts:
OPERATION B (Only for NAR Market)

Part number	Description	Q.ty
4M0959655BE	Airbag Control unit (NAR Market)	1

OPERATION C (For All Markets except the NAR Market)

Part number	Description	Q.ty
4M0959655BH	Airbag Control unit (ROW Market)	1



Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation B: 3.50 h

Operation C: 3.50 h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the "LIASS" system on the Lamborghini portal and, following the instructions in the system's "Manuals" section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.

The screenshot shows a web interface with a 'Header' section. Below it, there is a 'Cost Code' dropdown menu. The selected option is '50 Service Campaign'. Other visible options include 'A-Test 1', 'B-Test 2', and 'C-Test 3'.

Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPERATION B:**
 - o Steps to be executed: 1
 - o Labour time: 3.50 h
- **OPERATION C:**
 - o Steps to be executed: 1
 - o Labour time: 3.50 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section "Service and Recall Campaigns":

The screenshot shows a form titled 'Automobili Lamborghini S.p.A. Campagne service assistenza e campagne di richiamo / Service- und Rückrufaktion / Service and Recall Campaign / Service et campagne de rappel / Campaña de Servicio y Llamada a Taller'. The form is divided into two main sections, each with a header and a body. The headers are 'Servizio Assistenza' and 'Rückrufaktion / Service and Recall Campaign'. The bodies contain various fields for recording service and recall campaign details, including dates, locations, and specific actions taken.

Tools/Materials required

Code	Description.	Q.ty
n/a	n/a	n/a



NOTE:

All ODIS technical documentation can be viewed on the Lamborghini web portal, in the ODIS section.

L636- A.16.25	To: After Sales Official Network Subject: Airbag ECU replacement Date: 28/07/2025 Pages: 3	
--------------------------	---	--

OPERATION B: Airbag Control Unit Replacement **[Only for NAR Market]**

Insert VIN and follow the instructions given in the Workshop Manual at the following path:

1. Airbag ECU – Replacement procedure

SRS Passive Safety System > SRS > SRS Control Unit and Impact Sensors > Airbag ECU J234 (DA 15) > Disassembly/Assembly.

OPERATION C: Airbag Control Unit Replacement **[For All Markets except the NAR Market]**

Insert VIN and follow the instructions given in the Workshop Manual at the following path:

1. Airbag ECU – Replacement procedure

SRS Passive Safety System > SRS > SRS Control Unit and Impact Sensors > Airbag ECU J234 (DA 15) > Disassembly/Assembly.



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service

Rev.01 CONFIDENTIAL	The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.	3/3 Doc. no.: L/V6_M06 Rev.[07]
----------------------------	---	--