



Service Bulletin

Bulletin No.: PIP6077

Date: July, 2025

PRELIMINARY INFORMATION

Subject: 8T45 VT40 P07E5 / P073E No Drive and / or No Reverse

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025		All	All	All	All
GMC	Terrain	2025		All	All	All	All

Involved Region or Country	U.S. Only
Condition	Some Chevrolet and GMC vehicles equipped with the 8T45 MGH or VT40 MRQ automatic transmission may experience: No drive and or no reverse and a SES light on with code/s P07E5 and or P073E after an Over The Air update.
Cause	Engineering is investigating the concern.

Correction

Engineering is requesting to gather some information from a few vehicles.

If the vehicle has not been worked on and has a customer concern of no drive and/or no reverse with a SES light on and DTC(s) P07E5 and/or P073E set current/history, then create a GM TAC case referencing this PI number and wait for further instructions.

Version	1
Modified	7/30/2025

