

Technical Service Bulletin

Topic	91 Service info: MMI diagnosis: event memory entry B127213 at diagnostic address 005F
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2078801/1
Level	EH
Status	Released for publishing
Release date	Jul 31, 2025

Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
005F - Information electronics 1	B127213: Connection between antenna amplifier 1 and antenna Open circuit		static

New customer code

Object of complaint	Complaint type	Position
vehicle service -> vehicle diagnosis -> Guided Fault Finding (GFF)	control modules, services -> with fault stored in the DTC memory	

Vehicle data

A6 e-tron

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GH*	2025	A		*	*	*

Documents

Document name
master.xml



Connection offline

Technical Service Bulletin

Transaction No.: **2078801/1**

91 Service info: MMI diagnosis: event memory entry B127213 at diagnostic address 005F

Release date: Jul 31, 2025

Condition

Customer states:

There is no customer complaint.

Workshop findings:

1. The following DTC is logged in diagnostic address 005F – control unit 1 for information electronics (intermittent/passive):
 - B127213 Connection between antenna amplifier 1 and antenna, open circuit
2. The DTC occurs when switching the rear window heating on.
3. At the same time, no radio reception issues can be detected which are relevant to the customer.

Technical Background

Activating the rear window heating may lead to the specified DTC being triggered.

Production Solution

In vehicles built from week 10/25 onwards, the DTC is no longer triggered when the rear window heating is activated.

Service

Please note the information shown in ODIS S regarding the specified DTC.

If there is no customer complaint, no repairs need to be carried out. In this case, you have permission to ignore the specified DTC.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2078801**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.