

GPOP - Issue Review System

Part Number: 5RM05DX9A\$

Part Description: Quarter trim panel

Issue Description: The dealer is unable to secure the tire inflator pump in the rear left quarter trim. Dealers need to order Mopar service kit (PN 68563446AA) to stow the inflator under 2nd row load floor. Requesting dealers to not replace the spare tire cover with canceled part 1/4 trim storage cover (5RM05DX9AH)