

UPS D020 – REAR RIGHT LAMP ASSEMBLY COSMETIC DEFECT

UPDATE PRIOR TO SALE – REAR RIGHT LAMP COSMETIC DEFECT	
AFFECTED MODELS	25MY Range Rover
VOLUME AFFECTED	469 US 105 CAN
REPAIR	A concern has been identified on certain vehicles, where the rear right lamp assembly may have been manufactured with a cosmetic defect. This does not meet the required standard, and the rear right lamp assembly must be renewed if after inspection a cosmetic defect is found to be present. c. 18% of the affected vehicles are expected to require a replacement part.
REPAIR TIME	0.1 hr + DIDO
CAMPAIGN LAUNCH	Repair bulletin launched on June 26th, 2025, for Canada. US bulletin launched on July 10 th , 2025
NOTES	Affected vehicles needed to have the repair completed prior to customer handover and delivery. Confirm affected vehicles in the warranty portal and BBSS. Complete the inspection to identify defective parts <u>before</u> placing any parts orders.