WRN4 Workshop Campaign — Reworking drain hose on heating/fresh-air unit

WRN4 Workshop Campaign - Reworking drain hose on heating/fresh-air unit

ID Number WRN4

Model(s) Taycan (Y1A/Y1B/Y1C)

Model Year(s) 2025
VIN List Attached
Number of Affected VINs 795

Issue Description A drain hose not manufactured according to specifica-

tions may have been installed on the heater/fresh-air unit on affected vehicles. As a result, it cannot be ruled out that moisture may enter the passenger compartment due to leaking condensation over the service life of the vehicle. To prevent this from happening, the drain hose in the passenger compartment on

the heating/fresh-air unit must be reworked.

What Porsche Centers Should Do Please arrange for this action to be carried out on the

affected vehicles during the next workshop visit or be-

fore the vehicles are handed over to customers.

(Solution available as of 07/17/2025)

Part Status Status 1
TI No. 134/24

Required parts

 V04015800DF
 Water drain hose
 1 unit

 99951265209
 Hose clamp
 1 unit

Warranty processing

1

Validity:

This workshop campaign will be carried out up to 03/10/2029 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1 to Scope 3: Reworking drain hose in the passenger compartment on the heating/fresh-air unit

Damage number WRN4 66 000

Repair code 2

Labor time 194 - 230 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

Attachments

1. WRN4 WS Campaign VIN List V3 07.17.2025 HT.xlsx