

WPR5 Workshop campaign with customer notification – rework transmission input shaft

WPR5 Workshop campaign with customer notification - rework transmission input shaft

ID Number	WPR5
Model(s)	718 (982)
Model Year(s)	2023 - 2024
VIN List	Attached
Number of Affected VINs	337
Issue Description	In the affected vehicles, a grease that does not meet the required specifications was used to grease the transmission input shaft. This means that corrosion cannot be ruled out on the transmission input shaft over the service life of the vehicle. For this reason, the transmission input shaft and the hub of the clutch plate (manual transmission) or the hub of the dual-mass flywheel (PDK) need to be degreased and re-greased with the specified grease.
What Porsche Centers Should Do	Please arrange for this measure to be immediately performed on the affected vehicles (Solution available as of 07/18/2025)
Part Status	Status 1
TI	No. 182/23
Customer Notification	To be posted later

Warranty processing

Validity:

This workshop campaign will be carried out up to 03.07.2030 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1 - 15: Rework transmission input shaft

Damage Code	WPR5 66 000
-------------	-------------

WPR5 Workshop campaign with customer notification – rework transmission input shaft

Repair Code 1

Labor time 834 - 1211 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [WPR5 WS Campaign VIN List 07.17.2025 HT.xlsx](#)