

REFERENCE:	TSB: 23-029-25 GROUP: 23 - Body	Date:	August 6, 2025	REVISION:	—
VEHICLES AFFECTED:	2024 - 2026 (B1) Jeep Renegade (Brazil) This bulletin applies to vehicles built on or after June 28, 2024 (MDH 0628XX) and on or before May 23, 2025 (MDH 0523XX).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North and South America markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> • Water infiltration in the CHMSL. 				
CAUSE:	Manufacturing issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-159, date of issue August 06, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly replacing the CHMSL.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-88-97	CHMSL - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.
08-50-88-98	CHMSL - Inspect and Replace (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.
Failure Codes	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68759819AA - MOPAR 7099058 - EMEA	Brake light	CHMSL

REPAIR PROCEDURE:

1. Check if there is water in the CHMSL [Fig. 1](#).



Fig. 1
CHMSL

2. Is there water in the CHMSL?
 - YES>>> Proceed to [Step 3](#).
 - NO>>> This bulletin has been completed. Use Inspect LOP (08-50-88-97) to close the active RSU.
3. Replace the CHMSL. Refer to the detailed procedures available in DealerCONNECT> Service Library> under: 5550D16 - Terceira Luz De Freio (Brake-Light) - Remoção/Recolocação.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.