

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title High Idle Speed at Startup After Recent Engine Shutdown		Ref. No. TJ 37422.1.0	
Issuer (Dept.) Technical Service		Issue Date 6/26/25	Status Date 7/15/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 2540	
Function Description Catalytic converter and emission control		Page Page 1 of 1	

DESCRIPTION:

If the vehicle exhibits a high idle speed (approximately 1400 RPM) for 1-3 minutes during a period of 30 minutes to 1 hour after being shut off, follow the instructions under "Service".

RPM: Revolutions Per Minute

CSC Customer Symptom Codes

Code	Description
AE	Idling/Uneven idle
AF	Idling/High idle/Unsure when/at all times

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	M1	BM1KERS					2025-9999		-	202417-999952
238	M1	BM1KERS					2025-9999		-	202417-999952
246	M1	BM1KERS					2025-9999		-	202417-999952
256	M1	BM1KERS					2025-9999		-	202417-999952

SERVICE:

No repairs are needed, this behavior is as intended and is according to design.

Warranty claim info:

Information only. No warranty claim is accepted for this TJ.

VEHICLE REPORT:

N/A