

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title EX90 - Software download issue to HUD		Ref. No. TJ 37453.3.0	
Issuer (Dept.) Technical Service		Issue Date 7/28/25	Status Date 7/30/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3651	
Function Description Electronic control unit		Page Page 1 of 1	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Changed distribution list

If there is a need to perform a HUD Reload, follow the advice under "Service".

CSC Customer Symptom Codes

Code	Description
1Z	Service/repair/Software update failed
KD	Head Up Display HUD/Does not work
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-9999		-	202417-999952

SERVICE:

Do not perform a HUD Reload.

HUD Reload has been removed from the Software Installation menu in VIDA.

If the HUD has been replaced and software needs to be installed, please create a "Support Needed" vehicle report, as this needs to be done manually.

Abbreviations:

HUD - Heads up display

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a TIE Report to get assistance. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3651.