



Service Bulletin

Bulletin No.: PIP6046A

Date: August, 2025

PRELIMINARY INFORMATION

Subject: 6T40 6TH gear surge 55 to 70 mph

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envista	2025		All	All	LIH	MNH
Chevrolet	Trax	2025		All	All	LIH	MNH

Involved Region or Country	North America, South Korea
Condition	Some Buick and Chevrolet vehicles equipped with the GF6 6T40 automatic transmission may experience: a surge 55 to 70 mph in 6th gear concern.
Cause	Engineering is investigating the concern.

Correction

Test the vehicle to see if the surge is only there in 6th gear by shifting manually to 5th gear.

If the vehicle has the surge concern in only 6th gear, engineering has found this to be caused by a software anomaly

Bulletin 25-NA-211 address the concern for the LBP/MNH Engine/ Transmission build, but has not yet been released for the LIH/MNH build

In the meantime, please advise customer they may continue to drive the vehicle.

The PI will be removed and bulletin 25-NA-211 updated when a service calibration becomes available for the LIH/MNH Engine/Transmission build

Version	3
Modified	02/14/2025 - Created on 07/29/2025 - Replaced By bulletin 25-NA0 8/07/2025 - Updated to add engine and edit correction field

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.