



Service Bulletin

Bulletin No.: PIP6080

Date: August, 2025

PRELIMINARY INFORMATION

Subject: Diagnostic Tip For Stock Units With Low Power / Lack Of Acceleration LSD 1.5L

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2026		All	All	1.5 LSD	All
GMC	Terrain	2026		All	All	1.5 LSD	All

Involved Region or Country	North America
Condition	New stock unsold units may exhibit a lack of acceleration or low power.
Cause	Under investigation currently.

Correction

Engineering is currently investigating this concern. If any of these units present a lack of acceleration as a new unsold stock unit, please obtain a session log of engine data, induction data, and ignition data to submit for TAC for Brand Quality and Engineering review. Once the session logs are obtained, to correct the concern perform a battery disconnect for several minutes then reconnect and re-evaluate.

Version	1
Modified	08/08/2025 created on.

