



# Service Bulletin

Bulletin No.: PIT6338A

Date: August, 2025

## PRELIMINARY INFORMATION

**Subject: Lane Keep Assist Inoperative or Cannot Program FVCM**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado ZR2	2024		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	MAH / MBC, UHY, ZR2 - UKI / UKW / ULV
<b>Condition</b>	Lane Keep Assist system inoperative. Can turn on and off but there is no dynamic function.
<b>Cause</b>	Engineering is investigating this concern, please do not replace parts for this issue.

### Correction

In the meantime, please advise the customer they may continue to drive the vehicle.

The current concern may be a potential customer dissatisfier, but it is not a Safety Issue and does not create a substantial loss of use or value.

The PI will be updated or replaced with a TSB once a determination has been made.

If programming of front view camera module is attempted, a programming error will occur.

This will require Techline support to resolve. Do not replace the front view camera module.

### Additional SI Keywords

departure warning

<b>Version</b>	2
<b>Modified</b>	Created on 2/14/2025 Archived 7/28/25 replaced by TSB 25-NA-205 Re-instated on 8/20/2025

