



SSM 54142 2025 Expedition/Navigator - Whistle/Humming Noise Above 60 MPH (96 Km/H) From Right Side Of The Dash With A/C Turned On And Recirculation Mode On

Some 2025 Expedition/Navigator vehicles may experience a whistle/humming noise while driving in hot climates and at speeds above 60 mph (96 km/h). This noise can originate from the right side of the instrument panel when the air conditioning (A/C) system is ON, recirculation mode ON, and the noise intensity may increase as the blower speed is increased. Inform the customers Ford is aware of the concern and engineering is currently working on a solution for this condition that is expected to be published by 30-Sep-2025. This concern does not affect vehicle durability and customers can continue to drive the vehicle. Monitor Professional Technician System (PTS) for additional information and schedule a service appointment for customers once the repair becomes available.