



## STAR ONLINE PUBLICATION



**Case Number:** S2505000006

**Release Date:** August 2025

**Symptom/Vehicle Issue:** Ebooster Electronic Booster Service Information.

**Discussion:** Parts return analysis shows damage in the brake system consistent with contamination or the usage of unapproved lubricants/fluids. Ensure all fluids and lubricants used are MOPAR approved products. MOPAR lubricants and fluids, such as MOPAR brake fluid and White Lithium grease, are compatible with the rubber and plastic components. Pay close attention to avoiding introducing contaminants into the Ebooster including from tools and work area. Refer to Service Library for further information.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**