

|                            |   |
|----------------------------|---|
| <b>Field Action Number</b> | N25-250307  |
| <b>Release notes</b>       | <p>GM Update N25-250307</p> <ul style="list-style-type: none"><li>• Updates to reduce erroneous engine alerts.</li><li>• Improvements to accuracy of alerts.</li></ul> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p> |
| <b>Model Year</b>          | 2023<br>2024  |
| <b>Make</b>                | Chevrolet<br>GMC  |
| <b>Model</b>               | Silverado<br>Sierra   |
| <b>Components</b>          | ECM (Engine Control Module)   |