

UPDATE PRIOR TO SALE H557 – F-PACE SVR REAR BUMPER VALANCE

UPDATE PRIOR TO SALE H557 – F-PACE SVR REAR BUMPER VALANCE	
AFFECTED MODELS	26MY F-PACE SVR
VOLUME AFFECTED	111 USA 44 CAN
REPAIR	A concern has been identified on certain vehicles where the rear bumper cover may have been manufactured where clips required to provide the rigidity of the bumper cover have not been installed. As a result, the bumper cover will be overly flexible and away from the intended, permissible amount of flexibility. New retaining clips will be required on vehicles that fail inspection.
REPAIR TIME	Inspection 0.1 hr + DIDO
CAMPAIGN LAUNCH	Vehicle quarantine notice announced on July 29th, 2025. Vehicle Inspection bulletin published on August 8th, 2025
NOTES	Retailers are required to hold all affected vehicles that are within their control and complete the inspection procedure. Any vehicles that fail inspection must continue to be held pending publication of repair instructions and parts. USA Ports of entry are completing inspection and repair of affected vehicles under JLR control. All applicable VIN applicability are immediately flagged in the warranty portal and in BBBS.