

OIL LEAK FROM THE TRANSFER CASE

Customer Voice:

- Oil leaks from the transfer case area of the vehicle.

Technical Description:

- Damage to front input shaft seal or rear output shaft seal.

Status:

- If an oil leak is present at either seal:
 - Do NOT clean any oil from the transfer case.
 - Do NOT remove or disturb the oil seals.
 - Replace the transfer case following: TOPIx Workshop Manual section 315-00C General Procedures – Removal and Installation – Transfer Case.
 - Please submit an EPQR with pictures of the leak and reference to this SSM where engineering will arrange collection via the Parts Return Process(PRR).

SSM 76344

Range Rover

- 22-24MY Range Rover
- 23-24MY RR Sport

Defender

- 22-24MY Defender

Discovery

- 21-24MY Discovery

