

SHOCK ABSORBER DTCs

Customer Voice:

- The suspension warning light is on.

Technical Description:

- CHCM DTCs C1071, C1072, C1073, C1074, C1075, C1076, C1077 and or C1078 may be stored.

Status:

- Engineering are currently investigating this concern.
- **SSM 76367** has been published to provide repair guidance.
- Please do not replace any parts unless instructed to following the repair instructions.

Range Rover

- 22MY-On Range Rover
- 23MY-On RR Sport

