

 Connection offline

Vehicle-specific service

Topic	01 PSS Engine MIL on, DTC P050A00 Idle Speed Control stored in ECM
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2079008/1
Level	EH
Status	Released for publishing
Release date	Aug 19, 2025

Vehicle data

B10 A5 and Q5 Models

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		DXB*	*	*
GU*	2025	A		DXC*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
*	*	FU	*	S	*	000000	999999		
*	*	GU	*	S	*	000000	999999		

Documents

Document name
master.xml

Condition

Customer states:

MIL/exhaust emissions warning light is displayed in instrument cluster.

Workshop findings:

The following DTC is stored in the Engine Control Unit J623 (address word 0001):

- **DTC P050A00:** Idle speed control, malfunction at cold start

Technical Background

Not applicable.

Production Solution

A technical solution is currently being implemented. The solution is planned to be available in Q4 2025.

Service

NOTICE

This PSS may apply to vehicles still within the new model launch repair authorization period!

- **For vehicles still in the launch phase, the workshop must create a web ticket with the Technical Assistance Center (TAC) per the repair authorization, in addition to entering vehicle into PSS. Reference this TSB in the first line of the TAC case.**

1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern. Please clear the stored fault mentioned above in workshop findings and release vehicle.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

The complaint only occurs in rare situations and does not impact vehicle wear.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0040		
Labor Operations:	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol

	GFF / Guided Functions	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2079008/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2079008**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.