

## Technical Service Bulletin

<b>Topic</b>	01 Engine: engine oil pressure sensor P2D8F00 - EA888evo5 2.0 TFSI
<b>Market area</b>	United States 444 Volkswagen of America, Inc. (6444)
<b>Brand</b>	Audi
<b>Transaction No.</b>	2079097/1
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Aug 29, 2025

### New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> warning display symbols -> oil pressure loss warning display	functionality -> activates without cause	
information, navigation, communication, entertainment -> malfunction display symbols -> emissions control system malfunction display	functionality -> activates	
information, navigation, communication, entertainment -> warning display symbols -> oil pressure loss warning display	functionality -> activates	
information, navigation, communication, entertainment -> malfunction display symbols -> emissions control system malfunction display	functionality -> activates without cause	

## Vehicle data

---

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		DXBA	*	*
GU*	2025	A		DXCA	*	*

## Documents

Document name
<a href="#">master.xml</a>

## Condition

### Customer States:

- Warning display in instrument cluster.

### Workshop Findings:

The following DTC and symptom code is logged in -J623- (address word 0001):

- **P2D8F00** (symptom 17004) – Engine Oil Pressure Sensor/Switch “C” Circuit Low.

## Technical Background

The event memory entry is logged due to the control unit calibration.

## Production Solution

Not applicable.

## Service

- Please delete the event memory in the diagnostic log and reassess the complaint.
- If the event memory is logged again, please work through the event memory according to the Guided Fault Finding.

## Warranty

<b>Claim Type:</b>	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
<b>Service Number:</b>	1705		
<b>Damage Code:</b>	0010		
<b>Labor Operations:</b>	GFF– Checking and clearing fault codes included in existing labor operations	0150 0010	Time stated on the diagnostic protocol
	GFF	0150 0060	See SRT with associated operations
<b>Claim Comment:</b>	As per TSB 2079097/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2079097**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.