



Service Bulletin

Bulletin No.: PIT6395A

Date: August, 2025

PRELIMINARY INFORMATION

Subject: Lane Keep Assist Inoperative

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Tahoe	2025		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9C1 (Police Package Vehicle)
Condition	A customer may comment that Lane Keep Assist is inoperative and no DTCs are present.
Cause	Software Anomaly

Correction

To correct this concern, reprogram the K9 BCM with the latest calibrations in TLC/SPS.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Version	2
Modified	06/05/2025 - Created on 08/28/2025 - Updated Correction

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.