



Service Bulletin

Bulletin No.: PIT5578E

Date: August, 2025

PRELIMINARY INFORMATION

Subject: One Time use Heater Core Hose Clamps

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018 - 2024		All	All	All	All
GMC	Terrain	2018 - 2024		All	All	All	All

Involved Region or Country	North America
Condition	Heater core hose clamps may loosen after servicing the heater core inlet and outlet hose connections. This can cause a coolant leak into the vehicle interior.
Cause	Heater hose clamps are for one time use only.

Correction

The heater hose clamps are one time use and should be replaced whenever the connection is serviced.

Service Procedure:

Follow published service information in eSI.

Parts Information

Description	Part Number	Qty
Heater Hose Clamp	93190977	2

Version	6
Modified	07/26/2017 - Created on. 09/25/2017 - Update Model Information 01/27/2020 - Added 2019 and 2020 MY 01/29/2021 - Added 2021 MY 01/25/2022 - Added 2022 MY. 08/26/2025 - Added 2023 and 2024 MY.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.