



Service Bulletin

Bulletin No.: PIC6618

Date: August, 2025

PRELIMINARY INFORMATION

Subject: Front Compartment Lid May Not Open With First Button Press

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2025		All	All	All	All

Involved Region or Country	North America
Condition	Some customers may find that if the vehicle has been sitting idle for an extended amount of time, if they try to open the front compartment using the exterior touchpad (located on the front fascia, underneath the LH headlamp) that the exterior lamps will flash, but the front compartment lid may not open. If the exterior touchpad is pressed a second time, the front compartment lid will open as expected.
Cause	A potential software concern is under investigation for this issue.

Correction

If this concern is encountered, please refrain from replacing any hardware on the vehicle as an attempt to repair this condition. This document will be updated once a software solution becomes available.

As a reminder, on any C8 generation Corvette (model year 2020+), if the front compartment lid will not open for any reason, the customer always has the backup manual method available to him or her. All of these vehicles are equipped with a manual release pull-cable for the front stowage compartment. It is located inside the cabin, down near the brake pedal.

Version	1
Modified	08/29/2025 Created on.

