

McLaren GT & GTS – Vehicle Software Platform 4.14 MY20, 5.7 MY21, 6.7 MY22, 7.5 MY23, 8.4 MY25, and 9.0.1 MY26

Bulletin type:	Service Campaign
Reference number:	N/A
Campaign reference:	SCB 22 M 004
Attention:	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians
Affected vehicles:	McLaren GT & GTS
Situation:	A new software platform has been released to update the McLaren GT & GTS to the latest software 4.14 for MY20, 5.7 for MY21, 6.7 for MY22, 7.5 for MY23, 8.4 for MY25 and 9.0.1 for MY26.
Procedure:	Action affected vehicles on first opportunity (immediately if already on site or during next Retailer visit if not already on site). Please refer to the information outlined in this document to complete the required work
Date:	8 th August 2025

This bulletin will cover:

-
1. Overview
 2. Procedure
 3. Re-Programming Procedure
 4. Warranty Information
 5. Affected Vehicles
-

1. Overview

McLaren Automotive has released new software platforms to update the McLaren GT to version 4.14 for MY20, 5.7 for MY21, 6.7 for MY22, and 7.5 for MY23. McLaren GTS is required to be updated to version 8.4 for MY25 and 9.0.1 for MY26. The software update will include improvements and bug fixes to improve the customer driving experience.

2. Procedure

To carry out the Service Campaign for the Software Platforms 4.5 and 5.2 update, software updates in multiple control units are required using McLaren Diagnostic System (MDS) 2.

Please refer to the next section which contains the relevant work instructions and care points.

3. Re-Programming Procedure

Care Point: When using MDS 2 to update the vehicle to the newest platform, **DO NOT** use MDS 2 version 1.23

For McLaren GT MY20, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 4.14 – McLaren GT MY20**’ attached with this Service Campaign Bulletin.

For McLaren GT MY21, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 5.7 – McLaren GT MY21**’ attached with this Service Campaign Bulletin.

For McLaren GT MY22, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 6.7 – McLaren GT MY22**’ attached with this Service Campaign Bulletin.

For McLaren GT MY23, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 7.5 – McLaren GT MY23**’ attached with this Service Campaign Bulletin.

For McLaren GTS MY25, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 8.4 – McLaren GTS MY25**’ attached with this Service Campaign Bulletin.

For McLaren GTS MY26, please follow the instructions and care points within the document ‘**Installation Instructions Platform Release 9.0.1 – McLaren GTS MY26**’ attached with this Service Campaign Bulletin.

Care Point: Specific flashing order is required for successfully updating the vehicle software platform to 4.14 for MY20, 5.7 for MY21, 6.7 for MY22, 7.5 for MY23, 8.4 for MY25 and 9.0.1 for MY26. Always follow the correct control unit flashing order and instructions as specified in the installation instruction document and care points within

Care Point: Refer to Knowledge Article; KA-01038, ‘GT Series (P22) Current Software Platform’

4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
McLaren GT & GTS – Vehicle Software Platform Update 4.14/5.7/6.7/7.5/8.4/9.0.1	0.75 hrs

Care Point: If previous software platform versions are required to be updated prior to carrying out the work on this Service Campaign, add the additional time to the Warranty Claim. Where additional time is required, the McLaren Warranty department will review and may request justification

5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.