

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Interior

Topic: Water ingress into door modules or door harness

Condition: N/A

Diagnostic Trouble Codes: N/A

Measure

In the event of customer complaints for window operation or the internal or external door switches, it is recommended to inspect the door module and harness for signs of water ingress.

If signs of water ingress can be identified to either component please raise a Technical Request for further guidance.

Parts Information

Refer to MSP for latest information.

Attachments

N/A