

# WSH9 Workshop campaign - Re-programming high-voltage battery control unit

---

## WSH9 Workshop campaign - Re-programming high-voltage battery control unit

ID Number	WSH9
Model(s)	911 Carrera GTS (992)
Model Year(s)	2025
VIN List	Attached
Number of Affected VINs	1,756
Issue Description	A software error in the high-voltage battery control unit, can cause an unauthorized red warning message "Risk of fire! Stop and immediately leave the vehicle in a roadworthy manner" to be displayed on the instrument cluster. To prevent this, the high-voltage battery control unit must be reprogrammed with an optimized status on the affected vehicles.
What Porsche Centers Should Do	Please arrange for this action to be carried out on the affected vehicles ( <b>Remedy available as of 08/12/2025</b> )
California PCs Only	The Department of Motor Vehicles (DMV) in California may require that the customer furnish proof of completion of this Workshop Campaign in the form of a copy of the dealer's repair order, including a signed "Proof of Correction" certificate, before the next renewal of the vehicle registration. You must supply this documentation to the customer only after the campaign has been completed. Please instruct the customer to retain the signed "Proof of Correction Certificate" within their vehicle records.
Part Status	<a href="#">Status 0</a>
TI	<a href="#">WSH9</a>

### Required software

PIWIS Tester 4 test software release	43.500.000 (or higher)
--------------------------------------	------------------------

## Warranty processing

### Validity:

The present workshop campaign is carried out by the date maintained in PCSS and then closed.

Please note that warranty claims can only be processed up to this date.

### Scope 1:

Damage Code	WSH966 000
Repair Code	1
Labor time	39 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

---

### Attachments

1. [WSH9 WS Campaign VIN List V3 07.24.2025 HT.xlsx](#)