

WRU8 Workshop campaign – Replacing tailpipe covers

WRU8 Workshop campaign - Replacing tailpipe covers

ID Number	WRU8
Model(s)	911 (992)
Model Year(s)	2025 - 2026
VIN List	Attached
Number of Affected VINs	23
Issue Description	During ongoing quality analyses, it was determined that exclusive tailpipe covers were installed on the affected vehicles that do not meet the required specifications. The air intake frame of the rear apron may become thermally deformed over the service life in conjunction with high thermal loads, such as during prolonged high-speed driving. Customers might consider this as a visual detriment. For this reason, the tailpipe covers must be replaced by optimized components on the affected vehicles.
What Porsche Centers Should Do	Please arrange for this measure to be performed immediately on the affected vehicles (Solution available as of 08/25/2025)
Part Status	Status 1 - Order as needed
TI	No. 208/24
Customer Notification	To be posted at a later date

Warranty processing

Validity:

This workshop campaign will be carried out by 09.04.2030 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1: Replacing tailpipe covers

- **Vehicles with exclusive sports tailpipes in titanium (M-no. 0P5)**

WRU8 Workshop campaign – Replacing tailpipe covers

Damage Code	WRU8 66 000
Repair Code	2
Working time	276 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [WRU8 Workshop Campaign for Field Managers V3 08.25.2025 HT.xlsx](#)