



STAR ONLINE PUBLICATION



Case Number: S2508000075

Release Date: September 2025


Symptom/Vehicle Issue: Integrated Trailer Brake (ITB) Switch Removal

Technician Observation: Technician is looking to remove or replace the ITB switch from the Instrument Center Stack (ICS) switch cover.

Repair Procedure: To avoid damage to the ITBM switch see below method of removal.



Pull down and straight out with limited upward force.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.