



Service Bulletin

Bulletin No.: PIT6053C

Date: September, 2025

PRELIMINARY INFORMATION


Subject:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022		All	All	All	All
Chevrolet	Silverado 1500	2023 - 2026		All	All	All	All
Chevrolet	Silverado 2500HD	2024 - 2026		All	All	All	All
Chevrolet	Silverado 3500HD	2024 - 2026		All	All	All	All
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022		All	All	All	All
GMC	Sierra 1500	2023 - 2026		All	All	All	All
GMC	Sierra 2500HD	2024 - 2026		All	All	All	All
GMC	Sierra 3500HD	2024 - 2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UV2
Condition	Some customers may comment that the Frontview Camera Washer Nozzle is leaking washer fluid.
Cause	Some drizzle / dribble from the front grille camera nozzle after using the windshield washers is normal. If a steady stream of washer fluid is leaking from the front grille camera nozzle there could be an issue with the check valve built into the windshield washer hose that connects to the washer pump.

Correction

If no other root cause is found, then the check valve is included with the windshield washer hose that connects to the washer pump (#1 below) and replace as necessary.



6444856

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2070500	Windshield Washer Pump Hose Replacement	Use Published Time

Version	4
Modified	08/25/2023 - Created on. 10/02/2023 - Added Model year and updated correction information. 03/27/2025 - Updated Model Year and Added Models 09/08/2025 - Updated Model Year and Cause information