

REFERENCE:	TSB: 08-298-25 GROUP: 08 - Electrical	Date:	September 10, 2025	REVISION:	—
VEHICLES AFFECTED:	2025 (KM) Jeep Wagoneer S This bulletin applies to vehicles built on or after January 01, 2025 (MDH 0101XX) and on or before March 19, 2025 (MDH 0319XX) equipped with a 12.3" Touchscreen Display (Sales Code RHY).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> Vented seat button is not visible creating the illusion the vehicle is not equipped with the option. 				
CAUSE:	Faulty Display Screen Module (DSM)				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-191, date of issue September 10, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly replacing the DSM.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-18-01-90	Module, Display Screen (DSM) - Inspect (1 - Semi Skilled)	6 - Electrical and Body Systems	0.2 Hrs.
08-18-01-91	Module, Display Screen (DSM) - Inspect And Replace (1 - Semi Skilled)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	68641592AG	Display Screen Module	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

1. Is the vented seat button both visible and operational?
 - YES>>> This bulletin is complete. Use Inspect LOP (08-18-01-90) to close this active RSU.
 - NO>>> Proceed to [Step 2](#).
2. Replace the DSM. Refer to the detailed procedures available in DealerCONNECT > Service Library > under: 08 - Electrical / 8E - Electronic Control Modules / Module, Display Screen (DSM) / Removal and Installation.
3. Using wiTECH, Clear any DTCs.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.