

## Seal Attached To B-pillar Trim On Rear Doors Cracked

---

Topic number	LI72.12-P-076175
Version	5
Function group	72.12 - Rear door
Date	9/15/25
Validity	MODEL 206 206.0 FIN "F" up to manufacturing date: 18.01.2023 206.0 FIN "R" up to manufacturing date: 23.02.2023 206.2 FIN "F" up to manufacturing date: 15.12.2023
Reason for change	Order from taskforce quality model series 206: If a problem is present on a page, the other page must also be replaced. This is intended to avoid a possible follow-up repair.

---

### Complaint

Seal secured to B-pillar trim on rear doors cracked in upper area, see picture 1.

Attachments	
File	Description
Bild 1.jpg	



## Cause

Production deviation at supplier of B-pillar trim.

## Remedy

Replace both B-pillar trims with optimized parts.

### Note:

Both B-pillar trim pieces on the vehicle should be replaced, even if only one currently has the complaint.

WIS-References		
Document number	Title	Note
AR72.12-P-1713WT	Remove/install front trim strip from window frame of rear door	

## Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and

# XENTRY Tips

---

provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

## Symptoms

Body > Door/Flap > Door > Door > Seal cracked/torn

Body > Door/Flap > Door > Trim > Loose

## Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2066907504			Outer left B-pillar trim molding	1		X
A2066907604			Outer right B-pillar trim molding	1		X

## Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			73A0407	
			73N0407	