

Update Title	N24-245213
Associated Field Action Number(s)	
Release notes	<p>Certain 2023-2024 model year Chevrolet Colorado / Silverado 1500 and GMC Canyon / Sierra 1500 vehicles equipped with a 2.7L engine (RPO L3B), may have an Engine Control Module (ECM) that does not sufficiently control fuel injector flow rate under certain driving conditions.</p> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2023
Make	Chevrolet GMC
Model	Colorado Canyon
Components	ECM (Engine Control Module)