


Title: BL1030 update**Applicability:** MY2025 Revero**Market Region:** All**PRIORITY:** See provided list**PURPOSE:** A software update for MY2025 Karma Vehicles

All MY25 vehicles in the field will all receive this update over the air. Should this update not be accepted, create a TSS case and follow the representative guidance to update the vehicle manually. When the prompt is received accept the download and wait for the vehicle to complete the process. After the download and install are complete, power down the vehicle restart, the DIS will show some activity, wait for this to complete the install, this is a unique two step update due to software and it is expected.



The new software IDs should be as follow for the affected modules.

Module	New BL1030 ID
CIU	25.34.81.2
DIS	05013481
HCU	055C_C1_12
HCUc	0568_01_41

This latest update involves a number of enhancements.

There is new software for Invictus, will be seen in those models only.

After updates all personalized settings and customizations in the touch panel will no be kept unchanged as the vehicle owner had saved these. There are improvements regarding powertrain and other battery energy calculations.

Now when using Karma Sync, select Revero and proceed to select Model Year 2025.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Update Bulletin

Year: 2025

System: Infotainment (94)

Sequence: 02

Title: BL1030 update

Applicability: MY2025 Revero

Market Region: All

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
N/A	N/A	N/A

Please contact the parts department (parts@karmaautomotive.com) and order this part by email if not available in on-line at time of repair.

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART: (use one of the parts for the complaint)

PART NUMBER	DESCRIPTION
C131181101106	CIU

LABOR CODES: (use one appropriate for the part(s) replaced)

CODE	DESCRIPTION	TIME	DEFECT CODE
00-99-20-74	MY2025 BL1030 Update	0.5	99-20-20-68

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for four (4) years from the in-service date or 50,000 miles for Model Year 2025 Revero