



## **SSM 54248 2023-2026 Corsair - Changing The Fan Speed Changes The Fan Speed Icon To A Different Language Character Or Symbol**

Some 2023-2026 Corsair vehicles may exhibit a concern when changing the fan speed, the fan speed display icon (OFF/AUTO/fan speed number) changes to a different language character or symbol. This may be due to the accessory protocol interface module (APIM) software. Replacement or reprogramming of the APIM will not resolve this condition. Inform customers that engineering is currently working on a solution for this condition and will be released via software updates delivered over-the-air (OTA) expected Q4 2025. Software will update automatically if vehicle connectivity is enabled in the vehicle's settings. Schedule a service visit for customers who have disabled vehicle connectivity or who report that they did not receive the update by October 2025. Monitor Professional Technician System (PTS) for additional information.