

M2+/SD+ Davco Fuel Water Separator – Fuse Panel Cover Incorrect

M2+/SD+ Davco Fuel Water Separator- Fuse panel cover incorrect

Campaign SF720


Published: 8/15/2025

Problem Details:

- The fuse panel covers have a 30 Amp specification for a location that is 25 amp.
- The Fuse itself is 25amp but the description on the cover is incorrect

Affected Models / Truck options/ Truck Population:

- 250 Vehicles



Production Containment:

- Unknown

No Yes

Field Containment (short term):

- Some vehicles reworked at Plant in Offline
- VIN list of escaped vehicles was sent to service engineering

No Yes

Root Cause:

- DAVCO changed the spec and the description on the panel was missed

No Yes

Long Term Corrective Action Plan:

- N/A

No Yes

Long Term Field Plan:

- Release campaign to install the correct fuse panel covers.

No Yes