

# Technical Service Bulletin

<b>Topic</b>	94 Service info: moisture deposits in taillights
<b>Market area</b>	United States 444 Volkswagen of America, Inc. (6444)
<b>Brand</b>	Audi
<b>Transaction No.</b>	2079298/1
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Sep 12, 2025

## New customer code

Object of complaint	Complaint type	Position
lighting, signaling -> exterior lights -> tail lamp	contamination -> dirty	
lighting, signaling -> exterior lights -> tail lamp	component, automotive fluids -> fogged	
lighting, signaling -> exterior lights -> tail lamp -> tail lamp lens	dimensional accuracy -> flush dimension incorrect	> no instruction <
lighting, signaling -> exterior lights -> tail lamp	component, automotive fluids -> foreign objects present	
lighting, signaling -> exterior lights -> tail lamp	leaks -> water entering	
lighting, signaling -> exterior lights -> tail lamp	component, automotive fluids -> cracked/broken	
lighting, signaling -> exterior lights -> back-up light -> back-up light lens	contamination -> dirty	
lighting, signaling -> exterior lights -> tail lamp	component, automotive fluids -> damaged	
lighting, signaling -> exterior lights -> brake lamp -> brake light lens	contamination -> dirty	

## Vehicle data

### Audi Q4 e-tron

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
F4*	2022	A		*	*	*
F4*	2023	A		*	*	*
F4*	2024	A		*	*	*
F4*	2025	A		*	*	*

## Documents

<b>Document name</b>
master.xml

 Connection offline

## Technical Service Bulletin

94 Service info: moisture deposits in taillights

Transaction No.: **2079298/1**

Release date: Sep 12, 2025

## Condition

### Customer states:

There is moisture/water, and/or dirt deposits at the lower edges of the taillights.

## Technical Background

For design reasons, the bottom section of the taillights is transparent. In very wet conditions (heavy rain, spray), water and (possibly) dirt may be deposited. The component is not damaged.



There is no reason to replace parts or attempt repairs. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

## Production Solution

Not applicable.

## Service

The function of the component is not affected.



**There is no reason to replace parts or attempt repairs. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.**

## **Warranty**

This TSB is informational only and not applicable to any Audi Warranty.

## **Additional Information**

All part and service references provided in this TSB (**2079298**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

**©2025 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.